

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. X5

CASS COUNTY LAND CORNER RECORD

T. 141 R. R7 M. 5TH Coordinates: X _____ Y _____
E 1/4 31 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Species	<u>MAPLE</u>	<u>MAPLE</u>		
Diameter	<u>7"</u>	<u>7"</u>		
Bearing	<u>S75W</u>	<u>N80E</u>		
Distance	<u>64KS</u>	<u>15KS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed SECRETARY OF STATE
Monument PROPORTIONAL LOCATION - NO EVIDENCE
OF ORIGINAL SET 1"x36" IRON POST W/
BRASS CAP 531 1/2 532
1919

Bearing Trees, Reference Objects

Species	<u>SPRUCE</u>	<u>BARNSWOOD</u>		
Diameter	<u>12"</u>	<u>12"</u>		
Bearing	<u>N4W</u>	<u>S19-30W</u>		
Distance	<u>338KS</u>	<u>119KS</u>		

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____