


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
NE4 Corner common to sections 3, 4 AND 33, 34 - 142-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>	<u>BL. OAK</u>
Diameter <u>5"</u>	<u>8"</u>	<u>12"</u>	<u>12"</u>
Bearing <u>S60W</u>	<u>S45W</u>	<u>N46W</u>	<u>N10E</u>
Distance <u>18 LKS</u>	<u>50 LKS</u>	<u>12 LKS</u>	<u>55 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By GLO
Location filed SECRETARY OF STATE
Monument FIND DECAYED WOOD STAKE - SET 2436" 11P.
W BRASS CAP - FALLS IN R.O.W. - SET 36" IN GROUND

Evidence of Subsequent Corner Restoration

Year of search 1959 By DNR-Engineering
Map & notes in File
Found Corner

T142N R28W
S33/S34
54/53
T141N
1931

Species	Bearing	Trees, Reference Objects
<u>R.OAK</u>	<u>R.OAK</u>	
Diameter <u>6"</u>	<u>10"</u>	
Bearing <u>S36W</u>	<u>N52W</u>	
Distance <u>118 LKS</u>	<u>139 LKS</u>	

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____