


Index No. A23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N/41 Corner common to sections 1 AND 36-142-28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument OST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Ironwood Ironwood  
Diameter 9" 5"  
Bearing S40E N55W  
Distance 15 LKS. 25 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed SECRETARY OF STATE  
Monument 1x36" 11 P. w/ BRASS CAP 1/4 S36  
PROPORTIONAL POSITION S1  
1918

Evidence of Subsequent Corner Restoration

Year of search 1987 By Walt Curo  
Certificate - Doc # 301667  
Find brass cap monument bent over, replaced  
with 2" x 5 1/2" 11 P. w/ marked brass cap

Bearing Trees, Reference Objects

Species MAPLE R. OAK  
Diameter 8" 20"  
Bearing S5E N55W  
Distance 30 LKS 28 LKS

Bearing Trees, Reference Objects

Red oak Red oak Maple  
15" 15" 8"  
S77E S39E S24W  
21.05' 14.85' 12.55'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curo - 1987

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_