


Index No. C16

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5H Coordinates: X _____ Y _____
C.E. 116 Corner common to sections 3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1921
Original monument 1x36" I.P.W/BASS CAP E/116 53 1921

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W.OAK W.OAK
Diameter 10" 5"
Bearing S31/4W N72W
Distance 44 LKS 90 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Oak Oak Cedar Post
9" 6" 4"x4"
S2W S38E East
28.20' 37.40' 10.1'

C-16

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Bill Okerman - 1972

1997 - MN/Dot - Found GLO Brass cap
32' South of Twp road and witnessed:
24" Poplar, S85°E, 3.65'*
20" Burr Oak, S2°W, 28.00'*
FS Post 4"x4", E1/4, 5.45'
*distance to copper nail and disk.

1999 - Certificate filed as #410192 by
James Kramer RLS #23168 on the
1997 info.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____