


Index No. C 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
C14 Corner common to sections 1



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1x36" I.P. w/ BRASS CAP C14 S1 1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species R.OAK BL.OAK _____
Diameter 24" 20" _____
Bearing S29W N16 3/4 W _____
Distance 81 LKS 87 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1987 By Walt Curo
Corner Certificate - Doc # 301674
Find GLO monument

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Burr oak Burr oak Burr oak
15" 11" 8"
N24E N9E N46W
46.60' 29.05' 35.00'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL CHERMAN - 1973
Certificate - Walt Curo - 1987

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____