


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
E1141 Corner common to sections LAND 6-141-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species N. PINE

Diameter 14"

Bearing S10W

Distance 222 LKS.

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1915 By N. D. GORMAN

Location filed COUNTY BOOK B' P 572

Monument FIND OLD GOVT B.T. 30" W. PINE S. 10W
222 LKS, ALSO FIND IRON POST
1917, J. H. FLYNN BOOK B' P. 589-591 FIND OLD GOVT B.T.
10' N. PINE STUMP S10W 222 LKS

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>W. OAK STUMP</u>
Diameter	<u>STUMP</u>	<u>9"</u>
Bearing	<u>S 65 W</u>	<u>N 46-20 E</u>
Distance	<u>164'</u>	<u>200'</u>

1917 B.T.S

Evidence of Subsequent Corner Restoration

Year of search 1979 By MILU STEFAN

GOVT RESURVEY PLAT "E-71" 5 1/2 x 5 1/2 x 24"
CONCRETE POST WITH 3" BRASS CAP.
1919, E. B. HORSZ. COUNTY BOOK "C" P. 347 FIND U.S. LIM.

Bearing Trees, Reference Objects

<u>W. OAK</u>	<u>W. OAK.</u>	<u>W. OAK</u>	<u>SIGN POST</u>
<u>6"</u>	<u>6"</u>	<u>6"</u>	<u>STEEL</u>
<u>N 48 E</u>	<u>N 65 E</u>	<u>S 56 E</u>	<u>EAST</u>
<u>47.36'</u>	<u>43.20</u>	<u>100.01'</u>	<u>24.8'</u>

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed SECRETARY OF STATE

Monument FIND 2" GALV. I.I.B. AND GOVT B.T.S 24"
N. PINE STUMP S10W 222 LKS SET 1 X 36" I.I.B.
W/BRASS CAP 36" IN GROUND
14
51/56

8" POPLAR S 5 1/2 E 325 LKS 1918

8" POPLAR N 22 3/4 W 282 LKS

1915- Gorman - also on micro film - roll 115 BK 90
P. 38

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - We H Curo - 1927
Doc # 301676
Find 6" concrete monument as set in 1928
by US Forest Service
12" Burr oak N 41 E 47.50'
10" Burr oak N 59 E 43.40'
12" Maple S 45 E 35.50'