


Index No. DE 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S-SE 1/64 Corner common to sections 1



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919  
Original monument 1x36" 1/4 W / BRASS  
CRP

TR  
1532  
AP3

S  
1919

Bearing Trees  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1987 By Walt Curo  
Corner Certificate - Doc # 301678

Bearing Trees, Reference Objects

<u>Burr oak</u>	<u>Burr oak</u>	<u>Burr oak</u>
<u>4"</u>	<u>8"</u>	<u>10"</u>
<u>N 30 W</u>	<u>S 78 W</u>	<u>S 7 E</u>
<u>26.00'</u>	<u>20.1'</u>	<u>4.90'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1973

Certificate - Walt Curo - 1987

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_