


T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 9 Corner common to sections 4, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
 Original monument POST

Bearing Trees

Species	Bearing	Distance
<u>POPULAR</u>	<u>POPULAR</u>	
Diameter	<u>12"</u>	<u>10"</u>
Bearing	<u>S 67 W</u>	<u>N 20 W</u>
Distance	<u>38 LKS</u>	<u>27 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURD  
 Location filed COUNTY SURVEY RECORD BOOK 8 P. 107  
 Monument SET 2 1/2 x 4 1/2" CAPPED IRON

Also on microf. film - roll 105 BK 60 P. 110

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO  
FILED AT: SECRETARY OF STATE SET 1x3 1/2"  
1. P. W/ BRASS CAP - PROPORTIONAL POSITION  
14 54  
59  
1918

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>J. PINE</u>	<u>J. PINE</u>	
Diameter	<u>8"</u>	<u>5"</u>
Bearing	<u>S 45 1/4 W</u>	<u>N 48 W</u>
Distance	<u>375 LKS</u>	<u>144 LKS</u>

E - 11

Subsequent Corner Restoration

Year surveyed 1923 By Miss. Hwy Dept.  
 Location filed B/W map in Recorder's office - 15 mi  
 Monument E of Walker to 12 mi W. of Renner  
Corner 0.5' N. of G

8/2001 - CCSO found 3/4" Pin,  
down 0.5', on & Hwy # 200  
and 1980 USFS witnesses.

Sign Post steel South, 43.2'  
11" W. Oak S 57° E, 111.9' to 16d  
11" W. Oak S 10° E, 89.8' to 16d  
6" N. Pine S 49° W, 90.3' to 16d

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_