


T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
 W 116 Corner common to sections 3 & 10



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed _____
 Original monument _____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 8/01 By CCSO
 Location filed file #2001.037
 Monument Found 1 1/4" Sq. Pin, down 0.7', on E Hwy #200.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species Ash N. Pine J. Pine
 Diameter 8" 11" 10"
 Bearing N42°E S20°E S32°W
 Distance 73.04* 58.44* 73.18*
 * distance to double head nail

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____