


Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 10 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>18"</u>	<u>14"</u>	_____
Bearing	<u>N 29 E</u>	<u>S 12 W</u>	_____
Distance	<u>108 LKS</u>	<u>120 LKS</u>	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CYRO

Location filed COUNTY SURVEY RECORD BOOK B P. 107

Monument SET IRON

1915 - Baldwin - microfilm - roll 105 BK 60 P 112  
End both Govt B.T.S. - set F.M. 2' x 4" 113

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO

FILED AT: SECRETARY OF STATE, IND 2' GALV. I.P.  
AND GOVT B.T.S. 24" N. PINE N 26 1/2 E 108 LKS, 20" N. PINE  
STUMP S 15 3/4 W 120 LKS, SET 1/4" 1.1 P. W/ BRASS CAP

1/4 53  
570  
1918

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>N. Pine</u>	_____	_____
<u>8"</u>	<u>5"</u>	_____	_____
<u>S 2 E</u>	<u>N 56 1/4 W</u>	_____	_____
<u>75 LKS</u>	<u>68 LKS</u>	_____	_____

E-15

Subsequent Corner Restoration

Year surveyed 1923 By Mina Awe Dept

Location filed R/W map in Recorder's office 1 1/2 mi E

Monument of Walker to 12 mi W. of Kegan  
Corner on Road 5 Sta. 444 + 74.5

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By ~~MSD~~ MN/DOT

Cert. of Loc. Doc. # 410186

Fd. Iron Pipe w/ cap RLS # 12266

<u>20" N. Pine</u>	<u>S 5° E</u>	<u>49.34'</u>
<u>20" N. Pine</u>	<u>S 5° W</u>	<u>56.50'</u>
<u>1 3/4" x 42' CMP (NE End)</u>	<u>S 50° W</u>	<u>60.70'</u>
<u>3" I.P. w/ cap (Floyd)</u>	<u>N 65° W</u>	<u>104.00'</u>
<u>Wood Post w/ Copper</u>	<u>N 50° E</u>	<u>51.67'</u>
<u>nail and disk</u>		

1999 - MNDOT. Cert. of Survey indicates monument noted above fnd.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_