


Index No. E 18

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W 1/16 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1918  
Original monument 1x36" N.P.W./BRASS W 1/16 52  
LAP 511  
1918

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species BL. OAK BL. OAK \_\_\_\_\_  
Diameter 32" 28" \_\_\_\_\_  
Bearing N 8 1/2 E S 65 1/2 W \_\_\_\_\_  
Distance 130 LKS 393 LKS \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1923 By M. nn. Hux Dept  
Location filed PLW map in Recorder's office - 15 mi. E  
Monument of Walker to 12 mi. W. of Remer.  
Corner 0.1' N. of G sta. 4857 29.0

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_