


Index No. F7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 8



EXISTING SURVEYS

Original Government Survey
Year surveyed 1918
Original monument 1x36" I.P. W/ BRASS
CAP N 1/4 1 58
1918

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species R. OAK N. PINE _____
Diameter 8" 7" _____
Bearing S 11 3/4 E S 53 W _____
Distance 453 LKS 412 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1972 By William Okerman
found GLO monument in good condition.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
Poplar Oak Oak
8" 9" 5"
N 71 E N 12 W S 28 W
10.30' 56.80' 29.00'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____