


Index No. F-69

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 544 Coordinates: X _____ Y _____
S-N 1164 Corner common to sections 8, 9



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1x36" I.P. w/BRASS
CAP

APR TR 1531	APR TR 1690
58	59
1918	

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman

Found GLO monument in good condition

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Oak	Birch	Birch
5"	9"	7"
N55E	S47E	S5W
33.20'	57.90'	56.50'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____