


T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 9 Corner common to sections 9, 10



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>BASSWOOD</u>	<u>POPULAR</u>
Diameter <u>14"</u>	<u>8"</u>
Bearing <u>S85W</u>	<u>N15E</u>
Distance <u>15 LKS</u>	<u>13 LKS</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed SECRETARY OF STATE  
Monument END DECAYED WOOD STAKE & GALT P.T.S. 14'  
POPULAR N14E 13 LKS, BASSWOOD 18" S84 W 15 LKS  
SET 1X36" I.P. W/ BRASS CAP

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman  
Set 5 1/2 x 5 1/2 x 24" concrete monument  
with brass cap.  
Cedar post 4"x4"x72" South 16.40'

Bearing Trees, Reference Objects

Species <u>PL. MAPE</u>	<u>W. OAK</u>
Diameter <u>10"</u>	<u>26"</u>
Bearing <u>N28 1/2 E</u>	<u>N32W</u>
Distance <u>184 LKS</u>	<u>139 LKS</u>

Bearing Trees, Reference Objects

<u>W. OAK</u>	<u>ASH</u>	<u>ELM</u>
<u>5"</u>	<u>6"</u>	<u>8"</u>
<u>N83W</u>	<u>N59W</u>	<u>N19W</u>
<u>15.70'</u>	<u>27.90'</u>	<u>43.90'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1972