Index No. G3-4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections _____

E-W 1/4 LINE (SHORE OF ISLAND LAKE)



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. w/BRASS CAP C 57/57 C SMC 1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	R.OAK	W.OAK		
Diameter	8"	5"		
Bearing	N28 3/4E	N28 3/4W		
Distance	298 LKS	262 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____