Index No. H 11-12

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____

W - SE 1/64 Corner common to sections 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. W/BRASS CAP

TR 1724 APR 78 1923

59 1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species			
Diameter			
Bearing			
Distance			

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1971 By William OKerman

Location filed _____

Monument Found GLO monument in good condition

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Oak	Oak	Oak
Diameter	10"	10"	8"
Bearing	N21 E	N37 W	N83 W
Distance	58.20'	61.00'	86.50'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____