


Index No. H 17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
5 1/16 Corner common to sections 10, 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918 5 1/16  
Original monument 1x36" 1/2 P. W/BRASS 510/511  
CAP 1918

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species W. OAK W. OAK \_\_\_\_\_  
Diameter 6" 6" \_\_\_\_\_  
Bearing N42 3/4 E S46-45W \_\_\_\_\_  
Distance 115 LKS 51 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman  
Location filed \_\_\_\_\_  
Monument Set 2 1/2" x 60" galvanized steel pipe  
filled with concrete and capped  
with 3" brass tablet.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species W. Oak Oak OAK OAK  
Diameter 6" 6" 9" 7"  
Bearing N42 3/4 E N45 W S44 W N89 W  
Distance 75.9' 30.1' 77.3' 11.1'

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_