Index No. H 7-8

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____

E-SE 1/16 Corner common to sections 8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. W/BRASS CAP

TR 1331 AP3 38 1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species			
Diameter			
Bearing			
Distance			

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman

Location filed _____

Monument Found GLO monument in good condition

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Maple	Oak	Aspen
Diameter	8"	8"	11"
Bearing	S58W	S35E	N82E
Distance	17.2'	30.7'	30.3'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____