


Index No. H 8

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
SE 1/16 Corner common to sections 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument N 36° 11' P. W. / BRASS 5E 1/16 SB
CAP 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Poplar R. OAK _____
Diameter 5" 6" _____
Bearing N 58° E N 86 1/2° W _____
Distance 7 LKS 127 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1972 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Oak Oak Oak
Diameter 10" 6" 15"
Bearing N 39° E N 21° W N 76° W
Distance 61.70' 51.50' 37.80'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____