


Index No. J10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
w/116 Corner common to sections 9,16



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1918  
Original monument 1x36" I.P. w/BRASS w/116 59  
CAP 1918

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species N. Pine N. Pine \_\_\_\_\_  
Diameter 8" 8" \_\_\_\_\_  
Bearing N1W S107/4W \_\_\_\_\_  
Distance 63 LKS 75 LKS \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1972 By William Okerman  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species N. Pine N. Pine N. Pine  
Diameter 21" 17" 19"  
Bearing N77E N6E S14E  
Distance 80.60' 56.30' 41.80'

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_