


T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>POPULAR</u>	<u>POPULAR</u>
Diameter	<u>6"</u>	<u>5"</u>
Bearing	<u>N39W</u>	<u>N48E</u>
Distance	<u>18 LKS</u>	<u>88 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1917 By E.B. HORST  
Location filed COUNTY BOOK "B" P 601-603  
Monument FIND OLD GOVT POST & BT STUMPS: 6" POPULAR N39W 18 LKS, 5" POPULAR N48E 88 LKS - SET HUB

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLD  
FILED AT: SECRETARY OF STATE PROPORTIONATE POSITION -  
NO ORIG. EVIDENCE SET 2x36" I.P. W BRASS CAP  
T141N R28W  
510 | 511  
515 | 514

Bearing Trees, Reference Objects

Species	<u>OAK STAKES</u>	_____	_____
Diameter	<u>NE, NW</u>	_____	_____
Bearing	<u>SE, SW</u>	_____	_____
Distance	<u>46.7'</u>	_____	_____

Bearing Trees, Reference Objects

	1918		
Species	<u>POPULAR</u>	<u>R. OAK</u>	<u>W. OAK</u>
Diameter	<u>10"</u>	<u>14"</u>	<u>14"</u>
Bearing	<u>N70 1/2 E</u>	<u>S1 1/2 E</u>	<u>S3 W</u>
Distance	<u>423 LKS</u>	<u>447 LKS</u>	<u>540 LKS</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1992 Certificate David Landecker  
Doc. # 334681  
Found 2"x60" iron pipe with brass  
cap up 20". Ties: 20" Burr Oak N19 W  
457.33'; 15" Burr Oak S20E 332.36'; 8 1/2"  
Burr Oak S32 W 199.28'.

Sept. 2002 R. Mustonen 11946  
Cert. of Surv. shows mon. found.