


Index No. J 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 20 M. 5TH Coordinates: X _____ Y _____
E 1/16 Corner common to sections 12, 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" I.P.W. BRASS E 1/16 S1R
CAP 513
1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>POPLAR</u>	<u>POPLAR</u>	<u>CORNER IN ROAD</u>
Diameter <u>6"</u>	<u>8"</u>	<u>- SET 36" IN ROAD</u>
Bearing <u>S 58.45W</u>	<u>N 36W</u>	
Distance <u>76 LKS</u>	<u>99 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman
found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Clump	Bearing	Trees	Reference	Objects
<u>W. OAKS</u>	<u>W. OAK</u>	<u>W. OAK</u>	<u>W. OAK</u>	
<u>8"</u>	<u>7"</u>	<u>6"</u>		
<u>N 59 E</u>	<u>N 44 W</u>	<u>S 10 W</u>		
<u>43.40'</u>	<u>59.50'</u>	<u>82.70'</u>		

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared _____

Filed at _____ By _____

Date _____