


T. 141 R. 20 M. 5TH Coordinates: X NE 13 Corner common to sections 12, 13 AND 7, 18-141-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>W. OAK</u>	<u>BIRCH</u>	<u>POPULAR</u>	<u>BR. OAK</u>
<u>14"</u>	<u>6"</u>	<u>6"</u>	<u>5"</u>
<u>S15E</u>	<u>NORTH</u>	<u>S57E</u>	<u>WEST</u>
<u>30 LKS</u>	<u>10 LKS</u>	<u>33 LKS.</u>	<u>33 LKS</u>

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURD  
 Location filed COUNTY SURVEY RECORD BOOK 'A' P 564-567  
 Monument FND ROOTS OF POSSIBLE B.T.S.  
1914 JAMES MADDETON BOOK 'B' P 277-281 SET  
1/2" DRIFT BOLT  
1915, M.A. GORMAN BOOK 'B' P 272 FND COR. SET BY  
also - on MICROFILM - roll 45 BR 92 P 35 MIDDLETON  
 Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. PINE</u>	<u>R. OAK</u>	_____
<u>28"</u>	<u>10"</u>	_____
<u>S3W</u>	<u>N4-55E</u>	_____
<u>44.10'</u>	<u>39.90'</u>	_____

Evidence of Subsequent Corner Restoration

Year of search 1917 By J. H. FLYNN  
BOOK 'B' P 589-591 FND OLD GOVT B.T. STUMP  
16" W. OAK S15E 30 LKS,  
1979, MILO STEFAN, GOVT RESURVEY PLAT "E-71"  
24 3/8" I.P. w/ BRASS CAP.  
 Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. PINE</u>	<u>ASPEN</u>	_____
<u>9"</u>	<u>7"</u>	_____
<u>N40-15E</u>	<u>N47-50W</u>	_____
<u>68'</u>	<u>82.4'</u>	_____

1917 TIES

(OVER)

Subsequent Corner Restoration

Year surveyed 1918 By GLD  
 Location filed: SECRETARY OF STATE  
 Monument FND 1" I.P. AND GOVT B.T.S: 12" DECAYED  
PINE STUMP S86 3/4 W 33 LKS, 12" DECAYED OAK STUMP  
S87 3/4 E 30 LKS SET 2x 3/8" I.P. W/ BRASS CAP  
7141 N

Species	Bearing	Distance
<u>12" W. PINE</u>	<u>N42 1/2 E</u>	<u>104 LKS</u>
<u>6" W. OAK</u>	<u>S66 E</u>	<u>177 LKS</u>
<u>14" R. OAK</u>	<u>S69 1/4 W</u>	<u>260 LKS</u>
<u>10" POPULAR</u>	<u>N45 3/4 W</u>	<u>124 LKS</u>

1918

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1969  
Certificate David Landecker 1992  
Doc. # 334686  
Found 2" iron pipe with brass cap flush.  
TIES: 8" Burr Oak N31E 45.00'; 12" White  
Pine stump N42 1/2 E 68.64'; 15" White  
PINE N52E 79.20'; 10" Burr Oak S64E  
26.10'; 14" Red Oak stump S69 1/4 W  
171.60'; 7" Burr Oak N58 W 46.20'.