


T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
M.C.# 31 Corner common to sections 8, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>DEAD W. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>15"</u>	<u>20"</u>	_____
Bearing	<u>N 51 E</u>	<u>S 63 E</u>	_____
Distance	<u>80 LKS</u>	<u>106 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
 Location filed SECRETARY OF STATE
 Monument 1 X 36" I.P. w/ BRASS CAP

	<u>T141N</u>
	<u>SB</u>
<u>M.C.</u>	<u>517</u>
	<u>R28W</u>

1918

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>BIRCH</u>	<u>MAPLE</u>	_____
Diameter	<u>5"</u>	<u>7"</u>	_____
Bearing	<u>N 72 E</u>	<u>S 25 1/4 E</u>	_____
Distance	<u>37 LKS.</u>	<u>53 LKS</u>	_____

Bearing Trees, Reference Objects

Birch	<u>Maple</u>	<u>Oak</u>
<u>5"</u>	<u>7"</u>	<u>5"</u>
<u>N 30 E</u>	<u>S 84 E</u>	<u>S 20 E</u>
<u>10.60'</u>	<u>9.80'</u>	<u>19.30'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972