


Index No. K16

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 1/16 Corner common to sections 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" I.P. w/BRASS CAP NE 1/16 S15 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species POPULAR POPULAR _____
Diameter 12" 14" _____
Bearing S 80 3/4 E N 27 3/4 W _____
Distance 156 LKS 79 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Oak Oak Oak
5" 14" 10"
S 36 W S 76 W N 44 W
7.50' 70.90' 7.30'

K-16

Subsequent Corner Restoration

Year surveyed 1997 By Landecker Assoc
Location filed Walker office
Monument Found Brass cap
Certificate of survey indicates
monument in place.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____