


Index No. K17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N¹¹⁶ Corner common to sections 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" I.P. W/BRASS
CAP N¹¹⁴ 515 | 514
1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. OAK W. OAK _____
Diameter 12" 12" _____
Bearing S54 1/2 E S76 W _____
Distance 94 LKS 12 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Oak Oak Oak
7" 8" 7"
N 50 W S 87 E S 64 W
106.3' 5.4' 99.5'

Subsequent Corner Restoration

Year surveyed Feb 2000 By R. Mustonen *1946
Location filed _____
Monument Cert. of Surv. shows none found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____