


Index No. K-L 20

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S-NE 1/4 Corner common to sections 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" I.P. W/ Brass TR 1458  
CAP 1458 AP5  
AP2

Bearing Trees  
Species \_\_\_\_\_ 514  
Diameter \_\_\_\_\_ 1918  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman  
Found GLO monument.

Bearing Trees, Reference Objects

<u>Oak</u>	<u>Oak</u>	<u>Oak</u>
<u>5"</u>	<u>6"</u>	<u>6"</u>
<u>N31W</u>	<u>N18W</u>	<u>S65E</u>
<u>42.6'</u>	<u>30.0'</u>	<u>13.9'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_