


Index No. 219

CASS COUNTY LAND CORNER RECORD

T. 14 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C14 Corner common to sections 14



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1918  
Original monument 1x36" IR. w/BRASS C14 514  
CAP 1918

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. OAK W. OAK \_\_\_\_\_  
Diameter 10" 12" \_\_\_\_\_  
Bearing S41E S23W \_\_\_\_\_  
Distance 198 LKS 132 LKS \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1971 By William Okerman  
found GLO monument in good condition  
Cedar post 4x4x72" set North 1.20'

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
W. Oak Elm W. Oak  
9" 12" 19"  
S.33W N74W S24W  
60.60' 76.40' 87.50'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_