


Index No. L 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 514 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 114 19 Corner common to sections 13, 14



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1874  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1914 By JAMES MIDDLETON  
Location filed COUNTY SURVEY RECORD BOOK "B" P. 27-28  
Monument SET 1x1x20" DRIFT BOLT. 1

Evidence of Subsequent Corner Restoration  
Year of search 1918 By GLO  
FILED AT: SECRETARY OF STATE - PROPORTIONAL POSITION - NO ORIGINAL EVIDENCE SET 1x36" LP. W/ BRASS CAP.  
514/513  
1918

Bearing Trees, Reference Objects  
Species W. PINE STUMP W. PINE STUMP  
Diameter 32" 20"  
Bearing S37-52E N66-09W  
Distance 36.35' 44.85'

Bearing Trees, Reference Objects  
W. OAK W. PINE  
6" 8"  
S30 1/2 E N33 1/4 W  
38.6 LKS 33.1 LKS

Subsequent Corner Restoration  
Year surveyed Feb 2000 By A. Mustonen # 11946  
Location filed \_\_\_\_\_  
Monument Cert. of Surv. Shows Mon. Found  
OCT 2003 M. Landecker # 7452  
Cert. of Surv. Shows Mon. Found

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971  
Certificate David Landecker 1992  
Doc. # 334687  
Found 1" iron pipe with brass cap up  
5". TIES: 7" Norway Pine N64W 11.10';  
8" Norway Pine S54E 63.31'; 21"  
Norway Pine S48W 33.06'.

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_