


Index No. M-N 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 574 Coordinates: X _____ Y _____
5-51164 Corner common to sections 17, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
 Original monument 1x36" T.P. w/ BRASS CAP S18 TR 1563 APB 517
 Bearing 1918
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____
 Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1972 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>N. Pine</u>	<u>Tamarack</u>
<u>14"</u>	<u>19"</u>	<u>15"</u>
<u>S 5 W</u>	<u>S 19 E</u>	<u>S 81 E</u>
<u>140.30'</u>	<u>95.20'</u>	<u>120.30'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____