


Index No. N 10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
w 1/16 Corner common to sections 16, 21



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1918  
Original monument 1 x 3/16" i.p. w/brass w 1/16 516  
1 CAP 1918 571

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species J. PINE J. PINE \_\_\_\_\_  
Diameter 8" 8" \_\_\_\_\_  
Bearing N70E S41 3/4 E \_\_\_\_\_  
Distance 223.165 39.165 \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1973 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
J. Pine J. Pine W. Oak  
15" 16" 7"  
S40E S19E N52 W  
20.10' 32.30' 49.40'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1973

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_