


Index No. 0 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.N. 116 Corner common to sections 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" 11P. W/BRASS CAP N 116 S 521 1918

Bearing Trees	
Species <u>W. OAK</u>	<u>J. PINE</u>
Diameter <u>14"</u>	<u>8"</u>
Bearing <u>S 85 3/4 E</u>	<u>N 32 1/2 W</u>
Distance <u>104 LKS</u>	<u>393 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

<u>Elm</u>	<u>W. Oak</u>	<u>W. Oak</u>
<u>8"</u>	<u>10"</u>	<u>9"</u>
<u>N 84 E</u>	<u>S 57 E</u>	<u>S 34 E</u>
<u>31.20'</u>	<u>43.10'</u>	<u>50.90'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1974 Certificate - William Okerman

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_