


Index No. 0 12

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 57A Coordinates: X _____ Y _____
NE 1/16 Corner common to sections 21



EXISTING SURVEYS

Original Government Survey
Year surveyed 1918
Original monument 1x36" I.P. w/ BRASS NE 1/16 521
cap 1918

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species N. Pine J. Pine _____
Diameter 8" 6" _____
Bearing N 12 1/2 E S 69 W _____
Distance 42 LKS 69 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
N. Pine N. Pine N. Pine
20" 16" 15"
N 12 E N 54 E S 84 E
27.70' 61.50' 15.40'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____