


Index No. 0-P 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
MC # 3 Corner common to sections 23, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Species	Bearing	Trees
<u>J. Pine</u>	<u>OAK</u>	
Diameter <u>4"</u>	<u>9"</u>	
Bearing <u>N41W</u>	<u>N27E</u>	
Distance <u>28 LKS</u>	<u>60 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed SECRETARY OF STATE

Monument SET 1x36" I.P. W/BRASS CAP T141N/R28W
523/524
MC
1918

Evidence of Subsequent Corner Restoration

Year of search 1987 By Roger Mustonen

Corner Certificate - Doc # 302189

Find brass cap monument

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>J. Pine</u>	<u>POPLAR</u>	
Diameter <u>10"</u>	<u>6"</u>	
Bearing <u>N42E</u>	<u>N55W</u>	
Distance <u>121 LKS</u>	<u>107 LKS</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Birch</u>	<u>Ash</u>	<u>Maple</u>
Diameter <u>5 1/2"</u>	<u>6"</u>	<u>6"</u>
Bearing <u>S75E</u>	<u>S45W</u>	<u>N54W</u>
Distance <u>12.65'</u>	<u>4.44'</u>	<u>25.10'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Roger Mustonen - 1988

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____