


Index No. 0-P 19-20

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC ON. Corner common to sections \_\_\_\_\_  
N. LINE ALot 1635



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" I.P. w/ BRASS CAP

mc | S23  
/ S23  
TR 1635  
1918

Bearing Trees

Species	<u>ELM</u>	<u>W. OAK</u>	_____	_____
Diameter	<u>12"</u>	<u>8"</u>	_____	_____
Bearing	<u>S9 1/2 E</u>	<u>N11 1/2 E</u>	_____	_____
Distance	<u>57 LKS</u>	<u>150 LKS</u>	_____	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

plat - Green Acres - R.F. Schneider 1972

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_