


Index No. P 20-21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC on Corner common to sections \_\_\_\_\_

E-W 1/4 LINE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
 Original monument 1x30" IR w/BRASS CAP 523/C SMC 523/C 1918

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees

Species W OAK POPULAR \_\_\_\_\_  
 Diameter 14" 10" \_\_\_\_\_  
 Bearing S81W N81/4W \_\_\_\_\_  
 Distance 97 LKS 72 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Plat - Mance Shores, R.F. Schneider 1973

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_