


T. 141 R. 28 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 24 Corner common to sections 24 AND 19-141-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species IRONWOOD SUGAR MAPLE  
Diameter 4" 12"  
Bearing S45W N45E  
Distance 13 LKS 11 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURE  
Location filed COUNTY SURVEY RECORD BOOK 'A' P 564-567  
Monument SET 3x3x36" IRONWOOD STAKE PROPORTIONALLY  
1915, N. D. GORMAN BOOK 'B' P 571 FND CORNER  
also on microfilm - roll 115 BK 90 P. 27 - Fnd  
Maple B.T.

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO  
FILED AT: SECRETARY OF STATE FND 2" GALV. I.P.  
AND GOVT B.T. 18" MAPLE STUMP N45E 11 LKS,  
SET 1x36" I.P. w/BRASS CAP  
1/4  
524/519  
1918

Bearing Trees, Reference Objects

Species N. PINE STUMP N. PINE STUMP  
Diameter 20" 20"  
Bearing N63-25E S25-40W  
Distance 33.90' 40'

Bearing Trees, Reference Objects

MAPLE ELM  
14" 8"  
N75E S49 3/4 W  
24 LKS 157 LKS

Subsequent Corner Restoration

Year surveyed 1952 By HAROLD CURE  
Location filed COUNTY BOOK 'D' P 412  
Monument FND 2 1/2 x 48" GALV. I.P. W/CAP ALSO GLO  
BRASS CAP TIES:  
5" W. BIRCH N67-50W 19.40, 6" W. BIRCH S31-30E 15.10'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1973  
Certificate - Roger Mustonen - 1988  
Doc. # 302190  
Fnd brass cap monument  
7" Dead Maple N50E 24.10'  
12" Dead Birch S33E 16.40'  
5" White Oak S11 1/2 E 36.70'  
6" Basswood S33W 13.70'  
12" Red oak N67W 6.00'

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_