


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____
Original monument _____ C 1/4 S 20
1918

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. P 7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
c14 Corner common to sections 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" i.p. w/BRASS CAP c14 520 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species J. Pine J. Pine
Diameter 8" 7"
Bearing N42 1/2 E S41 1/2 W
Distance 47 LKS. 99 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

R. OAK W. OAK J. Pine
11" 13" 14"
N 87 E S 68 W N 18 W
21.00' 28.00' 53.00'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____