


Index No. R 13-14

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 18 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>W. PINE</u>	<u>W. PINE</u>
Diameter <u>10"</u>	<u>5"</u>
Bearing <u>N52W</u>	<u>S60W</u>
Distance <u>57 LKS</u>	<u>46 LKS</u>

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed SECRETARY OF STATE  
Monument PROPORTIONAL POSITION 1.82 CH. E (IN LAKE)  
SET 1X36" I.P. W/BRASS CAP

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species <u>POPLAR</u>	<u>POPLAR</u>	_____
Diameter <u>8"</u>	<u>6"</u>	_____
Bearing <u>S66 1/4 W</u>	<u>N48 1/4 W</u>	_____
Distance <u>60 LKS</u>	<u>16 LKS</u>	_____

Bearing Trees, Reference Objects

<u>J. Pine</u>	<u>R. Oak</u>	<u>W. Pine</u>
<u>10"</u>	<u>13"</u>	<u>11"</u>
<u>S 15 W</u>	<u>S 68 W</u>	<u>N 46 W</u>
<u>86.70'</u>	<u>20.10'</u>	<u>63.90'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_