Index No. R 19-15 CASS COUNTY LAND CORNER RECORD	
T. 141 R. 28 M. 574 Coordinates: X Y A.R. 2, ALOT Corner common to sections 22,27	
170/	
	G SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed 19/8 522	
Original manufact 1/2/4 1/2 1/10000 AP2	Year of search By
Original monument 1x 36" 11P. WIBRASS TRITOI CAP 527	Monument found
/4/36	O = Corner
bearing trees	Original Bearing trees round L
Species	Species
Diameter	Diameter
Bearing	Bearing
Distance	Distance
Cubas quanta Carra Basta and	
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed By	Year of search 1973 By William OKerman
Location filed	Found 610 monument in good condition.
Monument	V
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	Elm W. Oak N. Pine
Diameter	7" 5" 15"
Bearing	N12W 548W 531W
Distance	33.90' 4.70' 114.00'
Subsequent Corner Restoration Year surveyed By Location filed Monument	Evidence of Subsequent Corner Restoration Found Year of search By
Remonumentation certificate prepared	Date