


T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
NE 27 Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument lost

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>		
Diameter	<u>6"</u>	<u>9"</u>		
Bearing	<u>N18W</u>	<u>N32E</u>		
Distance	<u>27 LKS</u>	<u>26 LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

O = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument FOUND DECAYED WOOD STAKE & OLD GILT BRASS TAM
SPRUCE 10" N30E 26 LKS, TAM STUMP 8" N17W 27 LKS
SET 2X 36" I.P. W/ BRASS CAP T141N R28W
522 / 523

Bearing Trees, Reference Objects 527 / 526

Species	<u>TAM.</u>	<u>ROAK</u>	<u>J. PINE</u>	<u>RICH</u>	<u>1918</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>12"</u>	<u>10"</u>	
Bearing	<u>N22E</u>	<u>S29E</u>	<u>S51 1/4 W</u>	<u>N60W</u>	
Distance	<u>40 LKS</u>	<u>195 LKS</u>	<u>123 LKS</u>	<u>120 LKS</u>	

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary Stevenson
Corner Certificate - Doc # 303655
Found GLO monument

Bearing Trees, Reference Objects

Spruce	<u>5"</u>	<u>5"</u>	<u>TAM.</u>	<u>6"</u>
Bearing	<u>N50E</u>	<u>S45E</u>	<u>S25W</u>	
Distance	<u>19.44'</u>	<u>30.59'</u>	<u>28.52'</u>	

Subsequent Corner Restoration R 17

Year surveyed _____ By _____
Location filed _____
Monument Co DITCH SURVEY BK 103 BOX 3
OF Co DITCH SURVEY BOOKS, PG 19

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LIKEN'S NORTH SHORE BEACH
JOHN X STARK 1965
Certificate - Gary Stevenson - 1988
1999 - Freeman #21367 - Certificate
indicates GLO Brass cap found.
Apr. 2003 M. Stefan #12261
Cert. of Surv. shows Mon. Found