


Index No. R 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N1/4 25 Corner common to sections 24, 25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Species	Bearing	Trees
<u>BASSWOOD</u>	<u>MAPLE</u>	
<u>4"</u>	<u>12"</u>	
<u>N46W</u>	<u>S38E</u>	
<u>16LKS</u>	<u>16LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1987 By Roger Mustonen

Corner Certificate Doc # 302193

Set 2"x48" l.p. w/ stamped brass cap at proportional position

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>5"</u>	<u>S62E</u>	<u>20.22'</u>
<u>Red oak</u>	<u>14"</u>	<u>S83W</u>	<u>35.00'</u>
<u>Birch</u>	<u>16"</u>	<u>N7W</u>	<u>36.83'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Roger Mustonen - 1988

Re-monumentation certificate prepared _____ By _____

Filed at _____ Date _____