


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____ 1/4 _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____


Monument: _____

Monument: _____

Index No. R7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
N14 29 Corner common to sections 20, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Species	Bearing	Trees	Distance
<u>POPLAR</u>	<u>POPLAR</u>		
<u>7"</u>	<u>6"</u>		
<u>N18W</u>	<u>S10W</u>		
<u>24 LKS.</u>	<u>11 LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument PROBATIONAR POSITION SET 1x36" 1/8" W/
BRASS CAP. 1/4 520
529
1918

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. PINE</u>	<u>8"</u>	<u>S 83/4 W</u>	<u>17 LKS</u>
<u>J. PINE</u>	<u>10"</u>	<u>N 20 3/4 W</u>	<u>13 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N. Pine</u>	<u>19"</u>	<u>N 63 W</u>	<u>79.00'</u>
<u>N. Pine</u>	<u>17"</u>	<u>N 16 W</u>	<u>98.80'</u>
<u>Birch</u>	<u>10"</u>	<u>S 34 W</u>	<u>19.80'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____