


Index No. 5 13-14

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 57A Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC on Corner common to sections \_\_\_\_\_  
N 1/16 LINE



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1918  
 Original monument 1x36" 11P. W/BRASS CAP SMC N 527 N 527 N  
1918

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species ROSLAR ROSLAR \_\_\_\_\_  
 Diameter 8" 6" \_\_\_\_\_  
 Bearing N 20 1/4 E S 82 3/4 E \_\_\_\_\_  
 Distance 147 LKS 115 LKS \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search 1973 By William Okerman  
 Found GLO monument in good condition

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
W. Oak W. Oak W. Oak  
8" 8" 7"  
N 49 E S 88 E S 58 E  
34.30' 35.20' 14.00'

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
1974 Certificate - William Okerman

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_