


Index No. S 14-15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 57H Coordinates: X _____ Y _____

A.P. # 3 of Corner common to sections _____
ALOT 1701



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

TR
1701
A03
TR 1701
527
1918

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>10"</u>	<u>7"</u>	<u>7"</u>
<u>N 51 W</u>	<u>N 12 W</u>	<u>N 50 E</u>
<u>43.60'</u>	<u>30.00'</u>	<u>26.00'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1974

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____