


Index No. 57

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 574 Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x3/6" i.p. w/ BRASS CAP N 116 S 529
C 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>R. OAK</u>	<u>R. OAK</u>	_____
Diameter	<u>8"</u>	<u>7"</u>	_____
Bearing	<u>S51E</u>	<u>S51W</u>	_____
Distance	<u>143.05</u>	<u>149.65</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>11"</u>	<u>11"</u>	<u>9"</u>
<u>N84W</u>	<u>S53W</u>	<u>S37E</u>
<u>84.20'</u>	<u>83.90'</u>	<u>55.60'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____