


Index No. 59

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 Corner common to sections 28, 29



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1918  
Original monument 1x36" I.P.W/BRASS  
CAP

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

N 1/4  
529/528  
1918

Bearing Trees  
Species J. PINE W. PINE  
Diameter 8" 6"  
Bearing S17 1/4 E N49 3/4 W  
Distance 520 LKS 170 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

○ = Corner

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search 1973 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
N. Pine 17" J. Pine 12" W. Pine 12"  
N 73 W N 5 E S 17 E  
102.50' 125.70' 97.90'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1973

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_