


Index No. T11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
C114 Corner common to sections 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1 x 3/8" 1/2" W/ BRASS CAP C14528 1918

Bearing Trees		
Species	<u>N. PINE</u>	<u>R. OAK</u>
Diameter	<u>8"</u>	<u>12"</u>
Bearing	<u>S 1 1/2 E</u>	<u>N 10 3/4 W</u>
Distance	<u>139.45</u>	<u>213.45</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1983 (April) By Freeman-Hummitzsch
Location filed Survey Tech - Forester
Monument Found brass cap and the BTS of 1973
Oberman Corner (vert. Etc. - below)

Bearing Trees, Reference Objects			
Species	<u>R. OAK</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>5"</u>	<u>16"</u>	<u>21"</u>
Bearing	<u>N 76 W</u>	<u>S 13 E</u>	<u>S 1 E</u>
Distance	<u>17.00'</u>	<u>116.80'</u>	<u>91.74'</u>

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Oberman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>5"</u>	<u>16"</u>	<u>21"</u>
Bearing	<u>N 76 W</u>	<u>S 13 E</u>	<u>S 1 E</u>
Distance	<u>17.00'</u>	<u>116.80'</u>	<u>91.74'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OBERMAN - 1973

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____