


Index No. T-U 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N-S 1164 Corner common to sections 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" IR. W/BRASS 528

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects

<u>W. Pine</u>	<u>W. Oak</u>	<u>W. Pine</u>
<u>19"</u>	<u>6"</u>	<u>24"</u>
<u>N 50 W</u>	<u>N 19 E</u>	<u>N 84 E</u>
<u>26.90'</u>	<u>78.20'</u>	<u>87.80'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1971 Certificate - William Okerman

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_