


Index No. V 20

CASS COUNTY LAND CORNER RECORD

T. 14 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" I.P. w/ BRASS CAP E 1/4 SR6
535
1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>Tam.</u>	<u>Tam.</u>
Diameter <u>10"</u>	<u>8"</u>
Bearing <u>S 33 3/4 W</u>	<u>N 67 1/4 W</u>
Distance <u>53 LKS</u>	<u>29 LKS</u>

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Oberman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

<u>Tamarack</u>	<u>Tamarack</u>	<u>Tamarack</u>
<u>5"</u>	<u>5"</u>	<u>6"</u>
<u>S 18 W</u>	<u>S 18 E</u>	<u>N 36 E</u>
<u>22.30'</u>	<u>18.40'</u>	<u>42.20'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____

Filed at _____

Date _____